

## **What is the definition of the term linearity?**

The maximum deviation of the measuring signal between an ideal straight characteristic curve and the real characteristic curve is referred to as non-linearity or linearity. It is stated in per cent of the measuring range (% FS).