

When is zero correction required?

In order to compensate for any zero deviations which can be caused by temperature or ageing processes.